



Punchlister

Punchlist using your iPhone

Sample Reports

How is a certain subcontractor performing?

The following sample report is for the purpose of evaluating the performance of a specific subcontractor. It shows both the OK and No Good items that subcontractor is responsible for in a the same report, giving an overview of the performance of this particular subcontractor.

This document is only one example of the kind of reports that can be created by the Punchlister software. Using Punchlister, reports can be generated in real time through a convenient web-based user-interface that can be accessed by any computer connected to the Internet. These reports can be filtered by the status of items (OK, No Good, Not Punched Yet or all) and/or which subcontractor or subcontractors are responsible for the items. All reports are generated in a printer-friendly format for easy printing, faxing, and emailing.

For more information, please contact us toll-free at (866) 780-6555.

**EK Village
Punchlist Report**

Punchlister Development Company

Units: : 1A , 1B , 1C , 1D , 1E

Subcontractor : New York Plumbers

Filters : OK, NG

1. Floor - Unit: 1A

1 Bedroom

Bathroom : (as of 09/12/2008)

1A

Sink

OK Sink Caulking

OK Sink Faucet Leaking

OK Sink Fixtures

OK Sink Leaking

OK Sink Scratches

OK Sink Stopper Adjustments

Sprinkler

OK Escutcheon

Toilet

OK Toilet Caulked

OK Toilet Runs

OK Toilet Scratched or Damaged Lid

OK Toilet Scratched, Chipped or Dirty

OK Toilet Screwcap Missing

OK Toilet Seat Straight

Tub

OK Tub Calking

OK Tub Chipped Scratched or Dirty

OK Tub Faucet Leaky

OK Tub Stopper Adjusted

OK Tub Water Drains

Kitchen : (as of 08/29/2008)

1A

Dishwasher

OK Dishwasher Damaged

OK Dishwasher Not Leaky

OK Dishwasher Scratched or Dented

OK Dishwasher Works

OK Dishwasher Secure

Sink

OK Sink Caulking

OK Sink Faucet Leaking

NG Sink Installation	
NG Sink Scratched	
Sprinkler	
NG Escutcheon	
NG Sprinkler Leaks	
NG Stain on Ceiling	
1. Floor - Unit: 1C	
1 Bedroom	
Bathroom : (as of 09/22/2008) 1C	
Sink	
OK Sink Caulking	
OK Sink Faucet Leaking	
OK Sink Fixtures	
OK Sink Leaking	
OK Sink Scratches	
OK Sink Stopper Adjustments	
Sprinkler	
OK Escutcheon	
Toilet	
OK Toilet Caulked	
NG Toilet Runs	
OK Toilet Scratched or Damaged Lid	
NG Toilet Scratched, Chipped or Dirty	
OK Toilet Screwcap Missing	
NG Toilet Seat Straight	
Tub	
OK Tub Calking	
NG Tub Chipped Scratched or Dirty	
OK Tub Faucet Leaky	
OK Tub Stopper Adjusted	
NG Tub Water Drains	
Kitchen : (as of 08/16/2008) 1C	
Dishwasher	
NG Dishwasher Damaged	
OK Dishwasher Not Leaky	
NG Dishwasher Scratched or Dented	
OK Dishwasher Works	
NG Dishwasher Secure	
Sink	
NG Sink Caulking	
OK Sink Faucet Leaking	
NG Sink Installation	
OK Sink Scratched	

Sprinkler

OK Escutcheon

NG Sprinkler Leaks

OK Stain on Ceiling

1. Floor - Unit: 1E**1 Bedroom****Kitchen : (as of 09/03/2008)****1E****Dishwasher**

NG Dishwasher Damaged

OK Dishwasher Not Leaky

OK Dishwasher Scratched or Dented

OK Dishwasher Works

NG Dishwasher Secure

Sink

NG Sink Caulking

NG Sink Faucet Leaking

NG Sink Installation

NG Sink Scratched

Sprinkler

NG Escutcheon

OK Sprinkler Leaks

OK Stain on Ceiling